



October 22, 2004

Catholic Cemeteries
Diocese of Syracuse
2315 South Avenue
Syracuse, New York 13207

Attention: Mark Lazaroski

Re: Holy Trinity Cemetery
Whitestown, New York

Dear Mr. Lazaroski:

There are still problems with your Holy Trinity Cemetery Expansion Project that are impacting the Village of Yorkville. First, the 10" to 6" reducer on the outlet pipe from the detention basin has never been installed. In February 2001 you agreed to install this reducer. The Village of Yorkville agreed to allow you to tie into their storm sewer system only if you installed this reducer. It must be installed immediately. The grading along the west property line, the property line that runs along the rear yards of the Cross Street houses, has not been completed in accordance with the plans. The ditch that was suppose to be installed along this property line was never constructed. Storm water running down the hill is now running into the rear yards of the houses on Cross Street. A considerable amount of damage has occurred to the house located at 77 Cross Street. The owner has implied that this damage is the result of storm water running off of your property. These problems must be corrected immediately.

Please provide the Village of Yorkville a written schedule for the completion of this work.

Should you have any questions or comments concerning this matter, please contact me.

Very truly yours,

Zangrilli Engineering



Albert A. Zangrilli, PE

cc: Village of Yorkville
Bruno Petruccione, Mayor

Village of Yorkville,
Conrad Chaya, Highway Superintendent

Town of Whitestown,
Mathew Shannon, Town Supervisor

Town of Whitestown,
Karl Schrantz, Planning Board Chairman

Grever & Ward, Inc.
David G. Ward

Robert Ross